

# Clúster Logístico Manzanillo



**Lic. Ramón Castañeda Morán**  
**Delegado Federal en Colima**

**SE**

22 de Febrero de 2010

SECRETARÍA DE  
ECONOMÍA



ZONA HOTELERA  
MINATITLÁN  
MICHUACÁN



Autocamiones  
VENTAS REPARACIONES

Autos y Frenos  
TCH Y FRIENDS











FLH-H-02















































6 December 2010

Sr. Raúl Sandoval Calderón  
Transportes Hazesa  
Carr. Manzanillo-Minatitlan KM. 1.5  
Col. Tapeixtles, C.P. 28239  
Manzanillo, Colima

Estimado Sr. Sandoval:

I am writing to formally express our concerns about the condition of the street leading to the warehouse facilities Transportes Hazesa is providing for Minera Peñasquito – Avenida del Trabajo.

This street represents a huge safety and efficiency issue for all of the deliveries we are making to the warehouse, as well as your transport of our material for loading at the port. Some of the issues we have are:

- Unrestricted parking along both sides of the street by fuel trucks awaiting entry to the Pemex facilities which hamper vehicles safely maneuvering in and out of the Hazesa facility.
- The condition of the road itself. When it rains, the road becomes impassable, and flooding of adjacent warehousing occurs. When it dries, the ruts and potholes are a danger and significant problem to our truckers, particularly with all the unregulated parking. We have had several complaints from our trucking companies about the condition of the road as the potential for broken axels and other truck and trailer damage is getting worse. Accidents have already occurred.

It will become impossible for us to continue having materials hauled into this area or to expand the business as we had hoped without some very real improvements to the road. While we understand there is an underground channel process proposed as part of the remedy, we have an immediate need for improvement to the road surface itself.

Would you kindly discuss this with the appropriate officials in the Municipality and respond? We are very concerned about the negative impacts the condition of this street is having on our business.

With best regards,



Cheryl A. Sepestrom  
Senior Vice President, Metals Marketing

La calle que conduce a la bodega de HAZESA representa un problema de seguridad enorme y disminuye la eficiencia para todas las entregas que estamos realizando para el almacén, así como el traslado de nuestro material que se realiza hacia el puerto. Algunos de los problemas que tenemos son:

•No existen restricciones de estacionamiento en ambos lados de la calle para los camiones de combustible que se encuentran a la espera de entrar a las instalaciones de Pemex, lo cual obstaculizan que nuestros camiones de carga realicen de manera segura las maniobras de entrada y salida a la instalación de HAZESA.

•Las condiciones de la vía pública. Cuando la calle se seca, los surcos y baches son un peligro y un problema significativo para nuestros camiones. Hemos tenido varias quejas de nuestras empresas de transporte sobre el estado de las calles, ya que han ocasionado problemas en los camiones como, ejes rotos, remolques dañados y el daño es cada vez peor. Inclusive accidentes ya han ocurrido.

Se convertirá en imposible para nosotros seguir transportando los materiales en esta área o para ampliar el negocio.